



Tech Tips

TT 45-13-01

Date: May 31, 2013

2002-2005 Passat – Bosch 5.7 ABS Module Coding, ABS Fault 01044 “Control Module Incorrectly Coded”

After replacing a Bosch 5.7 ABS module, refer to the table below to determine correct module coding value based on vehicle PR codes. Listed login code must be entered under Access/authorization before coding is attempted. After completing coding, G85 steering angle sensor basic settings must be performed before cycling key. To perform G85 basic settings manually in Vehicle self-diagnosis (VAS PC) or Control Module OBD (ODIS), start by entering access/authorization code 40168. After code is accepted, turn steering wheel 1 turn left and back to center, one turn right, and then center steering wheel. Select basic settings and enter group 1. Once display changes to “Sensor OK” or “Calibration OK”, basic settings have been completed. Cycle key OFF and then back ON. Clear faults to verify repair.

Engine PR Code	ABS PR Code	Transmission PR Code	Login Code	Coding
T6T / T1K	1LT / 1LF	GOC / GOG / GOK / GOL	09355	04455
T6T / T1K	1LT / 1LF	GOF / GOQ	09357	04457
T0D	1LT / 1LF	GOC / GOG	09375	04475
T0D	1LT / 1LF	GOF	09377	04477
T0D	1LE / 1LB / 1ZC	GOC / GOG	09575	04275
T0D	1LE / 1LB / 1ZC	GOF	09577	04277
T7F	1LT / 1LF	GOC / GOG	09395	04495
T7F	1LT / 1LF	GOF / GOQ	09397	04497
T7F	1ZG / 1ZF / 1LC	GOC / GOG	09495	04395
T7F	1ZG / 1ZF / 1LC	GOF / GOQ	09497	04397
T7F	1LE / 1LB / 1ZC	GOC / GOG	09555	04255
T7F	1LE / 1LB / 1ZC	GOF / GOQ	09557	04257
T9H	1ZG / 1ZF / 1LC	GOL	08495	05395



Service Information

T9H	1ZG / 1ZF / 1LC	GOQ	08497	05397
T5X / T9J / T1E	1LE / 1LB / 1ZC	GOC / GOG / GOK / GOL	09555	04255
T5X / T9J / T1E	1LE / 1LB / 1ZC	GOE / GOF / GOQ	09557	04257
T0B / T10 / T6V / T0F	1LE / 1LB / 1ZC	GOC / GOG	09575	04275
T0B / T10 / T6V / T0F	1LE / 1LB / 1ZC	GOE / GOF / GOQ	09577	04277