

45800	Prior to removing the Hybrid Powertrain Control Module (SOBDMC) fuse cover on 2013-2016 Fusion, C-Max, and MKZ Hybrid Electric Vehicles (HEV) direct shop air to both sides of the area near the top of the fuse cover and between the top cover and the top cover of the SOBDMC to remove any moisture that may have collected in this seam.
-------	---