



TRP Number	Revision Level	Date	Group Number
T1479	E	29-JUL-2016	
Expiration Date (U.S. and Canada)		Expiration Date (International)	
31-DEC-2018		31-DEC-2018	



Temporary Repair Practice

ISX12/15 CM2350 - TRP to inspect for SCR compatibility.

Attention

- U.S / Canadian Distr./Branches and Div. Offices
- U.S / Canadian Dealers

This is to revise and replace TRP 1479-D, dated 03-Jun-2016. This revision is to:

1. Extend the expiration date to 31-Dec-2018.

If additional information is required, contact your Cummins Warranty Operations Group Leader.

Description

As new ECM calibrations are installed, the compatibility of the ECM calibration and the SCR catalyst **must** be maintained. This TRP is to allow for inspection of the SCR catalyst per TSB130099 when a new ECM calibration is installed during a repair event.

Action

In order to qualify for repair under this field action, an engine:

1. will be covered in the Base Engine or Emissions Control System Warranty period or CAP

Coverage period, and

2. the ESN **must** show as **OPEN** for this field action on QuickServe® Online, and
3. **must** have had an ECM calibration upgrade during the repair event.

After verifying that the engine meets the above requirements, perform the following actions:

1. Inspect the SCR Catalyst. Please refer to TSB130099 and follow the repair direction outlined.
2. Please file **only** for the inspection time (SRT 99-902) allowed to check the SCR Catalyst.

NOTE: ONLY inspection time (SRT 99-902) should be charged to this TRP. All other charges associated with the replacement of the SCR Catalyst and/or ECM recalibration can be claimed to the coverage that provides the most benefit to the customer including Base Engine Warranty, Emissions Control System Warranty or CAP coverage (if applicable) under failure code EQPEAW.

Material Disposition

There are **no** materials involved in the field action.

Reimbursements

Parts

There are **no** parts covered in this field action.

NOTE: SRT 99-902 is being provided to cover the labor with identifying the compatibility of the SCR catalyst according to the TRP procedure. This SRT can be claimed with up to a quantity of 2 (or .2 hours). 99-902 is the only claimable item for this TRP.

Labor using applicable Access Code and Time:

SRT Code	Description	Time (hrs)
99-902	SCR Catalyst Check (QTY 2)	.2

Travel

Travel is **not** covered under this field action. Towing is **not** covered under this field action.

Other Claimables

Consumables are **not** covered under this field action.

Claim Instructions

For Cummins Dealers, claims for this TRP **must** be filed via **RAPIDSERVE™** Web

(rsw.cummins.com). For information regarding **RAPIDSERVE™** Web, please reference the "Warranty" tab in QuickServe® Online. If there are additional questions, please contact your local Cummins Distributor.

ESN list, if attached, is for convenience. Actual eligibility is determined by the ESN's status for this field action on QuickServe® Online.

Claim Codes	
Description	Code
Account Code:	65
Pay Code:	Distributor = X
Pay Code:	Dealer = D
Pay Code:	International = I
Failure Code:	WEQPE9

Attachments

[Click here to see t1479-c_esn-list.xls](#)

[Click here to see t1479_ecm_revision_levels-attach-b.pdf](#)

[Click here to see t1479_non-compatible_and_compatible_pns-attach-c.xls](#)

Last Modified: 29-Jul-2016

Copyright © 2000-2010 Cummins Inc. All rights reserved.