



TRP Number	Revision Level	Date	Group Number
T1359	B	13-JUN-2014	
Expiration Date (U.S. and Canada)		Expiration Date (International)	
31-DEC-2014		31-DEC-2014	
Engine Family	Fuel System	Plant	Build Date
			From
ISX11.9	CM2250		



Temporary Repair Practice

ISX12 #1 Cam Bushing Failures TRP

Attention

- z U.S / Canadian Distr./Branches and Div. Offices
- z U.S / Canadian Dealers

This is to revise and replace TRP 1359-A, dated 06-Jun-2014. This revision is to:

1. Change primary contact to Robert Saxman.

If additional information is required, contact your Cummins Warranty Operations Group Leader.

Description

This TRP is being issued to grant approval to replace an engine that presents with the below symptoms and meets all listed criteria.

Action

In order to qualify for repair under this field action, an engine:

1. will be covered In the Base Engine Warranty period, and
2. **must** be on the attached ESN list, and
3. **must** have presented with a FC2322, and
4. the cylinder block in the area of the number #1 cam bushing **must** show signs of heat/discolored paint.

After verifying that the engine meets the above requirements, perform the following actions:

1. Create a Replacement Engine Request (RER).
2. Contact Cummins Heavy Duty Service Engineering Robert Saxman (Primary) 716-456-2238 or Justinian Engels (Secondary) 716-456-2540.
3. Contact **RAPIDSERVE™** Catastrophic for pre-authorization.
4. Remove the failed engine using Procedure 007-013 (Bulletin 2883445).

Material Disposition

Materials removed as a result of this field action **must** be sent to ReCon®.

Reimbursements

Parts

There are **no** parts covered in this field action.

NOTE: SRTs to gain access that are required to complete the repair, that are sufficiently explained in the claim narrative, may also be claimed on this action.

Labor using applicable Access Code and Time:

SRT Code	Description	Time (hrs)
00-115	Engine - Remove and Install (With EGR)	
00-90X	Administrative Time - Open and Close Repair Order (Shop Repairs)	

Travel

Travel is **not** covered under this field action. Towing is **not** covered under this field action.

Other Claimables

Consumables are covered under this field action.

NOTE: Included in the consumable value of the TRP is a swing engine and coolant top off.

Claim Instructions

For Cummins Dealers, contact **RAPIDSERVE™** Catastrophic for pre-authorization and claim

filing. If there are additional questions, please contact your local Cummins Distributor.

Claim Codes	
Description	Code
Account Code:	65
Pay Code:	Distributor = X
Pay Code:	Dealer = D
Pay Code:	International = I
Failure Code:	WBKBSN

Attachments

[Click here to see t1359-a_esn-list.xls](#)

Last Modified: 13-Jun-2014

Copyright © 2000-2010 Cummins Inc. All rights reserved.