



TRP Number	Revision Level	Date	Group Number
T1479	B	17-JUN-2014	
Expiration Date (U.S. and Canada)		Expiration Date (International)	
31-DEC-2018		31-DEC-2018	
Engine Family	Fuel System	Plant	Build Date
			From
ISX, QSX15ISX15 ISX11.9			



Temporary Repair Practice

ISX12/15 CM2350 - TRP to inspect for SCR compatibility.

Attention

- ε U.S / Canadian Distr./Branches and Div. Offices
- ε U.S / Canadian Dealers

This is to revise and replace TRP 1479-A, dated 11-Apr-2014. This revision is to:

1. Remove narrative from the Material Disposition Section, and
2. Revise Attachment C.

If additional information is required, contact your Cummins Warranty Operations Group Leader.

Description

As new ECM calibrations are installed, the compatibility of the ECM calibration and the SCR catalyst **must** be maintained. This TRP is to allow for inspection of the SCR catalyst and determine if it needs to be replaced during a repair event.

Action

In order to qualify for repair under this field action, an engine:

1. will be covered in the Base Engine or Emissions Control System Warranty period or CAP Coverage period, and
2. **must** be on the attached ESN list, and
3. **must not** already have a compatible SCR catalyst as per Attachment B.

After verifying that the engine meets the above requirements, perform the following actions:

1. Inspect the SCR Catalyst. Is SCR Catalyst compatible as per attachment B or TSB130099?
 - a. Yes - No further action is necessary. Please file for the inspection time (99-902) allowed to check the SCR Catalyst.
 - b. No - Please install a compatible SCR Catalyst. **ONLY** inspection time (99-902) should be charged to this TRP. All other charges associated with the replacement of the SCR Catalyst can be claimed to the coverage that provides the most benefit to the customer including Base Engine Warranty, Emissions Control System Warranty or CAP coverage (if applicable) under failure code EQPEAW.

Material Disposition

There are no materials involved in the field action.

Reimbursements

Parts

There are no parts covered in this field action.

NOTE: SRTs to gain access that are required to complete the repair, that are sufficiently explained in the claim narrative, may also be claimed on this action.

NOTE: SRT 99-902 is being provided to cover the labor with identifying the compatibility of the SCR catalyst according to the TRP procedure. This SRT can be claimed with up to a quantity of 2 (or .2 hours). 99-902 is the only claimable item for this TRP.

Labor using applicable Access Code and Time:

SRT Code	Description	Time (hrs)
99-902	SCR Catalyst Check (QTY 2)	.2

Travel

Travel is **not** covered under this field action. Towing is **not** covered under this field action.

Other Claimables

Consumables are **not** covered under this field action.

Claim Instructions

For Cummins Dealers, claims for this TRP **must** be filed via **RAPIDSERVE™** Web (rsw.cummins.com). For information regarding **RAPIDSERVE™** Web, please reference the "Warranty" tab in QuickServe® Online. If there are additional questions, please contact your local Cummins Distributor.

Claim Codes	
Description	Code
Account Code:	65
Pay Code:	Distributor = X
Pay Code:	Dealer = D
Pay Code:	International = I
Failure Code:	WUSSCZ

Attachments

[Click here to see t1479-a_esn-list.xls](#)

[Click here to see t1479_ecm_revision_levels-attach-b.pdf](#)

[Click here to see t1479_non-compatible_and_compatible_pns-attach-c.xls](#)

Last Modified: 17-Jun-2014

Copyright © 2000-2010 Cummins Inc. All rights reserved.