

# ***EVAPORATIVE EMISSION (EVAP) SYSTEM LEAK INSPECTION CHANGE***

Workshop Manual EVAP system leak inspection using the M-MDS has been discontinued for some models. Instead, the Workshop Manual EVAP system leak inspection using EVAP leak tester will be used to troubleshoot EVAP system leaks.

The EVAP system leak inspection using the M-MDS has been removed from IDS update (Version 100). Workshop Manual procedures will be revised soon to reflect this change.

## **Models affected by this change:**

- 2011-2015 Mazda2
- 2010-2016 Mazda3
- 2012-2016 Mazda5
- 2009-2017 Mazda6
- 2016-2017 CX-3
- 2013-2016 CX-5
- 2010-2012 CX-7
- 2007-2016 CX-9
- 2016 MX-5



**EVAP LEAK TESTER**

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication. © 2016 Mazda Motor of America, Inc.

To contribute repair tip ideas, send an e-mail to [mtips@mazdausa.com](mailto:mtips@mazdausa.com) or fax to (949) 442-6599. If we select your repair tip, you will receive \$50 value in Reward Performance by Mazda (RPM) points for your efforts. All contributions become property of MNAO, which assumes permission to publish them without further consideration