

Reference	SSM72926
Models	F-TYPE / X152 XE / X760 XF / X250 XF / X260 XJ / X351 XK / X150
Title	Rearview Mirror Temperature Sensor - Diagnosis and Testing
Category	Body
Last modified	07-Sep-2016 00:00:00
Symptom	103000 Mirrors
Content	<p><u>Issue:</u> Customer may report erratic ambient air temperature readings or default setting (ie.-40°) appearing.</p> <p><u>Cause:</u> Ambient air temperature sensor circuit signal fault.</p> <p><u>Action:</u> Please refer to workshop manual 5: Body and Paint / 501-09 Door mirror Diagnostic and Testing, Ambient air temperature sensor tests/resistance check.</p> <p>Carry out the diagnostic procedure highlighted in that section before replacing the sensor.</p>