



Tech Tips

TT 20-16-03

Date: September 23, 2016

**2015 – 2016 Touareg w/3.6l - Misfires on Cold Start – DTCS
P0300, P0301, P0302, P0303, P0304, P0305, P0306, May be
Setting, Fuel Quality is Suspect**

Review the GFF log and verify the misfires were set on cold start up ONLY. This will typically be at ambient temps below 10°C (50°F). It may also be beneficial to find out what brand and octane fuel the customer is using and if they use continually utilize the same filling station. Drain both sides of the Fuel Tank (**IT IS IMPERATIVE TO DRAIN BOTH SIDES OF THE TANK**). Add fresh Fuel (minimum of ½ tank) using Top Tier Fuel Premium Fuel. Clear all DTC's and road test 50 to 200 miles with multiple Cold start-ups. Please advise the customer to utilize Top Tier Fuel, of the correct Octane per their owner's manual.