

Navigation Position at Startup Incorrect; Audio Unit Presets Blank at Startup; Helicopter/CD Skipping Noise

AFFECTED VEHICLES

2016 Pilot EX and above

Do you have a vehicle in your shop for any of these issues?

- When starting up the vehicle, the navigation system position is incorrect.
- When starting up the vehicle, the audio unit presets are blank (there's no text in the boxes).
- When playing the audio unit with the **Neural** (surround sound) setting turned on, you hear a noise from the speakers that sounds like a helicopter hovering or a CD skipping.

We want you to know we have them under investigation and have found the root cause for all three. We'll be releasing an audio unit software update along with a service bulletin in early 2017.

Until then, don't replace any audio/navigation components for these issues.