



- Hide This Menu
- Acknowledgements
- Transactions
- Parts and Service News Flash
- Airbag Inflator Recall
- Service Information
- Vehicle Information
- eVRM-M
- Warranty
- Courtesy Delivery Claims
- Other Claims / Reimbursement
- ACPV XM Radio Demo Activation
- Remanufactured Parts
- Owner Info Change
- Service Bay
- Campaigns
- eResponsibility Report
- ACE Reporting
- Acura Experience
- Tech Line
- Marketing
- Customer Relations
- AcuraLink
- Performance Reports
- Perfect Delivery
- Brand Protection
- Acura Owners
- Accessory Sell Sheet
- Accelerated Service

- Quick Links
- Service Information
 - Parts Bulletins
 - tlc Roadside Assistance Ref Guide
 - Associate Status
 - Management Reports
 - Tool and Equipment Program

No Reported Market Ruptures Of A PSDI-5 Driver Front Airbag Inflator In A Honda Or Acura Vehicle As Of 3/28/2016 (Worldwide)



0:37 / 2:54