

[Next Unread Message](#)**View Message**

Sent on	02	19	2016	Expires on	03	03	2016
From	Parts and Service Division						
Subject	Request for Visit: 2015 TLX, 2016 ILX, MDX & RDX TPMS Light ON at TQI						

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
 From: Technical Research & Support Group
 RE: Request for Visit: 2015 TLX, 2016 ILX, MDX & RDX TPMS Light ON at TQI

**This message is solely directed to Acura dealership personnel; please handle accordingly.
 Print this i/N message and provide a copy to the Shop Foreman and all Service Consultants.**

Background

American Honda (AHM) is investigating certain 2015 TLXs, 2016 ILXs, MDXs, & RDXs with the TPMS light ON at TQI. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. TPMS light must remain ON.
2. If the TPMS light is noticed before starting the engine (ignition in Accessory mode (IGI)), leave the vehicle in Accessory mode without starting the engine.
3. If the TPMS light illuminates after starting the engine, leave the vehicle running.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.