
2015 TLX, 2016 ILX, MDX & RDX TPMS Light ON at TQI

Background

American Honda (AHM) is investigating certain 2015 TLXs, 2016 ILXs, MDXs, & RDXs with the TPMS light ON at TQI. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. TPMS light must remain ON.
2. If the TPMS light is noticed before starting the engine, leave the vehicle in that mode without starting the engine.
3. If the TPMS light illuminates after starting the engine, leave the vehicle running.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.