

---

## **2016 Pilot Rear Left Door Weatherstrip Loose/Deformed**

---

### **Background**

American Honda (AHM) is investigating certain 2016 Pilots with a customer complaint of wind noise coming from the rear left door are or a loose/deformed weatherstrip on the rear left door. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

### **Qualifiers**

AHM is interested **ONLY** if the vehicle meets the following requirements:

1. Must confirm deformed or distorted rear left door weatherstrip.
2. No previous accidents or repairs related to the rear left door weatherstrip.

### **Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.