

[Next Unread Message](#)[View Message](#)

<b>Sent on</b>	12	09	2015	<b>Expires on</b>	12	18	2015
<b>From</b>	Parts and Service Division						
<b>Subject</b>	Request for Parts: 2015 TLX Brake Judder						

**PRIORITY/ACTION REQUIRED**

To: All Acura Service Managers/Consultants  
From: Technical Research & Support Group  
RE: Request for Parts: 2015 TLX Brake Judder

This message is solely directed to Acura dealership personnel; please handle accordingly.  
Print this *iN* message and provide a copy to the Shop Foreman and all Service Consultants.

**Background**

American Honda (AHM) is investigating certain 2015 TLXs with a customer complaint of brake judder. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested ONLY if the vehicle meets the following requirements:

1. Must be able to duplicate the judder.
2. No previous repair relating to the front brakes.

**Action Required**

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.