



# Tech Tips

TT 87-11-01

Date: March 18, 2011

## 2011-2016 Jetta, 2012-2016 Beetle – A/C Control Module Basic Settings

**June 24, 2016: Update to Information.**

After A/C control module J301 is replaced, fault 00898-005 “Activation A/C Compressor No or Incorrect Basic Settings” may be stored. GFF test plan does not perform Activation A/C Compressor Basic Setting. To perform basic setting and resolve this fault, follow steps below:

**2011- 2015 Vehicles follow the below procedure:**

- Set the blower on position 1 or 2
- Set Airflow direction to “vent”
- Set Temperature to “full cold”
- Start the engine
- Press and hold the defrost and a/c buttons at the same time
- Hold the buttons for 5-7 seconds until the defrost, A/C, and recirc buttons are illuminated
- Restart the vehicle and recheck all functions before returning the vehicle to the customer

**2016 Vehicles follow the below procedure:**

- Under control module OBD, address 08, adaptation, enter 9 for the channel, then enter value 1 and apply. Retest operation.