



# Tech Tips

TT 87-11-01

Date: March 18, 2011

2011-2016 Jetta, 2012-2016 Beetle – A/C Control Module Basic Settings

June 10, 2016: Update to Model Year Applicability.

After A/C control module J301 is replaced, fault 00898-005 “Activation A/C Compressor No or Incorrect Basic Settings” may be stored. GFF test plan does not perform Activation A/C Compressor Basic Setting. To perform basic setting and resolve this fault, follow steps below:

- Set the blower on position 1 or 2.
- Set Airflow direction to “vent”.
- Set Temperature to “full cold”.
- Start the engine.
- Press and hold the defrost and a/c buttons at the same time.
- Hold the buttons for 5-7 seconds until the defrost, A/C, and recirc buttons are illuminated.
- Restart the vehicle and recheck all functions before returning the vehicle to the customer.