



Tech Tips

TT 91-16-11

Date: August 12, 2016

**2015 Beetle, Beetle Convertible, EOS, Jetta - RNS 315
Navigation Radio – Volume Knob Outer Ring Separated –
Service Part Available**

The customer may complain that the outer plastic ring on the RNS 315 Volume Knob/Power Button has separated and/or has fallen off of the knob (Fig. 1).

The RNS 315 Volume Knob/Power Button is now a part that is available separately.

Part No: 1K8 998 922 (RNS 315 Volume Knob Kit)



Fig. 1