

[Next Unread Message](#)**View Message**

**Sent on** 07 08 2015 **Expires on** 10 02 2015  
**From** Acura Parts, Service & Technical Division, Campaign Administration  
**Subject** Product Update: 2015 TLX & 2016 MDX Actuator Supply Circuit P0657

**TO:** All Acura Sales, Service & Parts Managers and Personnel  
**FROM:** Acura Parts, Service & Technical Division, Campaign Administration

**Re:** Product Update: 2015 TLX & 2016 MDX Actuator Supply Circuit P0657

Today, July 8, 2015, American Honda is announcing a product update for some 2015 TLX & 2016 MDX units for updating the PCM software to repair a concern that may cause the vehicle to unexpectedly shift into neutral during normal operation.

**Basic Problem**

While driving, the vehicle may shift into neutral unexpectedly, causing the transmission indicator to come on and DTC P0657 (actuator supply voltage circuit/open) to store. The driver will not be able to select any other gear until the vehicle is turned off and restarted.

**The Repair**

Update the TCM and PGM-FI software with improved versions.

**Service Bulletin**

S/B 15-034, *Product Update: Vehicle Shifts into Neutral and MIL Comes On with DTC P0657* has been posted on Service Information today in support of this product update, and it includes software, warranty and update information related to this PUD.

**Parts Information**

This is a software update only. Please refer to S/B 15-034 for more information.

**Client Notification**

American Honda expects to notify owners of affected vehicles in early August.

As always, please make sure to check iN VIN status to determine if a particular vehicle is eligible for this product update.

© 2000–2015, American Honda Motor Co., Inc. All Rights Reserved.