

---

**2013-2014 Accord Click or Pop Noise from the Driver's Airbag Area**

---

**Background**

American Honda (AHM) is investigating certain 2013-2014 Accords with a customer reporting a pronounced clicking or popping noise coming from the driver's airbag area while turning the steering wheel. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

**Qualifiers**

AHM is interested **ONLY** if the vehicle meets the following requirements:

1. First time complaints only and no previous repairs.
2. No prior accidents.
3. Must be able to duplicate concern.

**Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.