



SERVICE BULLETIN

Classification: EC16-012a	Reference: NTB16-035a	Date: March 13, 2017
------------------------------	--------------------------	-------------------------

2011-2017 JUKE AND 2017 SENTRA; TURBOCHARGER SERVICE

This bulletin has been amended. The Title and APPLIED VEHICLES section have been revised, and a PARTS INFORMATION section has been added. No other changes have been made. Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2011-2017 Juke (F15)
2017 Sentra (B17)

APPLIED ENGINES: MR16DDT

SERVICE INFORMATION

When a turbocharger on an Applied Vehicle is replaced for any reason, make sure to also replace the TUBE-TURBOCHARGER OIL FEED* (Oil Supply/Inlet Tube) listed in the PARTS INFORMATION, below.

PARTS INFORMATION

VEHICLE	DESCRIPTION	PART #	QUANTITY
2011-2014 Juke 2015-2017 Juke NISMO RS	TUBE-TURBOCHARGER OIL FEED (Oil Supply/Inlet Tube)	15192-1KC0E	1
2017 Sentra 2015-2017 JUKE 2015-2017 JUKE NISMO		15192-BV80A	

* This is the steel tube that feeds oil from the engine front to the turbocharger housing.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.