

Subject

**Rear Combination Lens Service Tips**

Market

USA

Service Category

Vehicle Exterior

Section

Lighting (ext)

Applicability

2013- 2015 FR-S

**APPLICABLE VEHICLES**

2014, 2013, 2015


FR-S

**CONDITION**

Effective 9/2013 the rear combination light housing and gasket were changed to reduce the possibility of insect intrusion into the rear combination light housing.

This Tech Tip is being published as a reference for using current level gaskets with previous level rear combination lights.

Do not use prior level gaskets on newer tail lights. It is permissible to install current level gaskets with previous level tail lights.

**RECOMMENDATIONS**Gasket change Detail**LINK REFERENCES**

This Tech Tip does not contain any link references