



Service Bulletin

PRELIMINARY INFORMATION

Subject: PQC Part Restriction - Airbag Sensing and Diagnostics Module

Models: 2003-04 Pontiac Vibe

This PI was superseded to remove part restriction. Please discard PIC5857A.

The part restriction on the parts listed below has ended. Thank you for your assistance in collecting data related to these part numbers.

These part numbers can now be ordered directly through your Parts Department without PQC authorization.

Note: PRIOR to replacing the module, be sure to follow the procedure called-out in the latest version of Field Action 13030.

The following parts are no longer on restriction:

19205561 - Airbag Sensing and Diagnostics Module (without side airbags)

19205562 - Airbag Sensing and Diagnostics Module (with side airbags)

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION