



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** PQC Part Restriction - Airbag Sensing and Diagnostics Module

**Models:** 2003-04 Pontiac Vibe

*This PI was superseded to change restriction from TAC to PQC. Please discard PIC5857.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

As part of our ongoing quality improvement efforts, the following Airbag Sensing and Diagnostics Modules are currently restricted through PQC:

19205561 - Airbag Sensing and Diagnostics Module (without side airbags)

19205562 - Airbag Sensing and Diagnostics Module (with side airbags)

### Recommendation/Instructions

Before considering replacement of the Airbag Sensing and Diagnostics Module, please review the latest version of Field Action 13030, document all of your results, and repair as necessary. If the concern is still present or if the diagnosis leads to replacement of the Airbag Sensing and Diagnostics Module, contact PQC to review your test results.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION