



Service Bulletin

PRELIMINARY INFORMATION

Subject: Information on Electronic Power Steering (EPS) Loss of Power Assist, DTC C0545 Set

Models: 2014 Chevrolet Caprice PPV, Chevrolet SS

Condition/Concern

Some customers may comment on loss of power steering assist and Service Power Steering message displayed on the DIC.

Technicians may find DTC C0545 set as current or in history.

Recommendation/Instructions

If the above condition exists, refer to Customer Satisfaction #14804.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION