



# Preliminary Information

## PIC6291 DTC Ignore List For 2018 RPO's IOS, IOT, and IOU

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Regal	2018	All	All	All	All
Cadillac	ATS	2018	All	All	All	All
Cadillac	CTS	2018	All	All	All	All
Cadillac	XTS	2018	All	All	All	All
GMC	Terrain	2018	All	All	All	All
Involved Region or Country	North America					
Additional Options (RPO)	IOS, IOT, IOU					
Condition	<p>When scanning a vehicle for Diagnostic Trouble Codes technicians may find DTC's that apply to components that the vehicle is not equipped with current in the radio. Technician may clear the Diagnostic Trouble Code but it will return. Technician should not replace any components for this concern. Technician can ignore the Diagnostic Trouble Code that is set if the vehicle is not equipped with the component. GM engineering is working on this concern and the PI will be updated or a bulletin created when further information is available.</p> <p>For all 2018 vehicles listed above with IOS, IOT, or IOU please ignore U18B2 and U0196</p> <p>Also ignore the following DTC's based on vehicle content (RPO code):</p> <p>Telematics Module (without UE1): ignore DTC's U18AF and U183A            External Amplifier (without UQA), (without UQS), (without UQG): ignore DTC U18B1            Digital Audio Broadcast (without U2Q): ignore DTC B125B</p> <p>Ignore U18B0 for the following instances:</p> <p>MY18 Regal (with IOS or IOT or IOU) and (without UDD) or (without UHS)            MY18 ATS (except China) (with IOS or IOT or IOU) and (without UDD)            MY18 Terrain (with IOS or IOT or IOU)</p>					
Cause	Radio Software Anomaly					

### Version History

Version	1
Modified	