

---

## **2013-2014 CR-V Rear Reflectors Loose or Missing**

---

### **Background**

American Honda (AHM) is investigating certain 2013-2014 CR-Vs with a complaint of the rear reflectors loose or missing (part # 33505-SLJ-013 for right rear reflector assembly or 33555-SLJ-013 for left rear reflector assembly). To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to your attempting a repair of any kind.

### **Qualifiers**

AHM is interested **ONLY** if the vehicle meets the following requirements:

1. VIN must start with 2HK.
2. Vehicle has not been involved in any collision.
3. No previous repair on the rear reflectors.

### **Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.