

Reference	SSM73358
Models	Discovery Sport / L550
Title	Rear Camera Replacement
Category	Electrical
Last modified	27-Apr-2017 00:00:00
Symptom	203000 Basic Electrical

Content**Issue**

Rear Camera replacement

Cause

A recent change has been implemented to the rear camera and Bezel and as a result they have to be changed as a matching pair as this could impact on the display of the guidance lines seen by the customer

Action

The following part numbers require the new Bezel

Part numbers listed below

- LR092728 - for 15 and 16 MY vehicles fitted with InControl Touch
- LR092733 - for 15 and 16 MY vehicles fitted with GEN2.1
- LR083805 - for 17 MY vehicles fitted with InControl Touch
- LR096450 – New Bezel

JLR eCAT is being updated to reflect this change

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.