




Service Bulletin

INFORMATION

Subject: Visible Rust on Replacement Wheel Bearing P/N 13582664

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Impala	2010	2010				

Involved Region or Country	North America
-----------------------------------	---------------



Technicians may comment when receiving wheel bearing P/N 13582664, a light rust coating is present under the white shipping cap once removed.

Cause	This condition is a known issue with the wheel bearings that are being shipped.
--------------	---

Correction	Engineering has determined no action should be taken and the wheel bearing is acceptable to use as received.
-------------------	--

Version	1
----------------	---

Modified	
-----------------	--

occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION