August 2017

ATS 170802 Version 1

Navigation Screen Clock Reads 00:00

AFFECTED VEHICLES

2000-03 Odyssey and 2003-05 Pilot

Is the navigation screen clock reading 00:00? We're aware of this issue and are looking for a solution.

Until then, **do not** replace any components. Doing so **won't** fix this issue.

© 2017 American Honda Motor Co., Inc. – All Rights Reserved