

[Previous Screen](#)

Welcome: chrismk2

◀ Product: NO EQUIPMENT SELECTED
 Model: NO EQUIPMENT SELECTED
 Configuration: NO EQUIPMENT SELECTED

Technical Information Bulletin

CT660 Vision Link "Ghost Codes" Instrument Cluster Generated Codes{7000}

Media Number -TIBU7283-00

Publication Date -18/09/2013

Date Updated -18/09/2013

Caterpillar: Confidential Yellow

i05453289

CT660 Vision Link "Ghost Codes" Instrument Cluster Generated Codes{7000}

SMCS - 7000

On Highway Truck:

CT660 (S/N: TGA1-UP; TGD1-UP; TEJ1-UP; TRK1-UP; TKL1-UP; TEP1-UP; TJS1-UP; TGT1-UP; TSW1-UP; TSY1-UP; TGZ1-UP)

Introduction

The problem that is identified below does not have a known permanent solution. Until a permanent solution is known, use the information that is identified below.

Problem

Ghost codes show up on Vision Link, but not on the ECM's.

The gauge cluster can generate some fault codes. The only way to read these codes are on Vision Link.

Solution

Table 1 shows the list of codes that can be generated from the gauge cluster. The codes in Table 1 are not ghost codes and should be investigated (troubleshoot).

Table 1

Real Codes Generated from the Gauge Cluster (for troubleshooting)			
Condition Description	SPN	FMI	DMI Warning Lamp
Loss of data link from Engine Controller	2000	9	MIL
Loss of data link from ABS controller	2011	9	
ABS warning lamp malfunction	1438	5	
Trailer ABS warning lamp malfunction	1792	5	
MIL warning lamp malfunction	1213	5	MIL
Wait to Start lamp malfunction	1081	5	MIL
Failure of non-volatile memory	2023	12	
Fault on Transmission Oil Temp sensor	177	3 or 4	
Fault on Fuel Level sensor	96	3 or 4	
Fault on Brake Primary Pressure Sensor	117	3 or 4	
Fault on Brake Secondary Pressure Sensor	118	3 or 4	

[Copyright 1993 - 2013 Caterpillar Inc.](#)

[All Rights Reserved.](#)

[Private Network For SIS Licensees.](#)

Wed Oct 2 17:09:36 CDT 2013

chrismk2