

**On-car analysis list from September 3rd, 2014  
please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
<b>Powertrain</b>	Touareg, Beetle, Jetta, Passat	14 - 15	1.4T, 1.8T, 2.0L (Jetta ONLY), 2.0T, 2.5L (Jetta ONLY), 3.0L	All	EVAP leak / EVAP circuit related faults, perform GFF, if GFF fails or does not provide a resolution contact the VW Technician Helpline	MIL-on
<b>Body</b>	Jetta	14	All	All	Car -Net Button	Car-Net button fell into the overhead console housing
	Passat	12 - 15	All	All	B-Pillar Trim	Customer states the B-Pillar trim is cracking
	Jetta	14	All	All	Front windows binding during operation causing false pinch protection activation or noise while operating the window  VIN range EM236581 to EM350000 or EM386721 to EM500000	Front window(s) binding or noise during operation
<b>Electrical</b>	Golf, GTI	15	All	All	HID headlamp w/ LED type DRL inoperative ONLY	Customer states the LED daytime running light strip does not light up
	Jetta	14 - 15	All	All	Horn activation on it's own	Customer states the horn beeps on it's own when driving/turning the steering wheel
<b>Chassis</b>	No Current Topics					