

Classification:

AT13-019b

Reference:

ITB13-035b

Date:

October 21, 2016

CVT FLUID LEVEL CHECK SERVICE INFORMATION

This bulletin has been amended. The **APPLIED VEHICLES** section has been revised.
No other changes have been made. Please discard all previous versions of this bulletin.

APPLIED VEHICLES: 2013 JX35 (L50)
2014-2017 QX60 (L50)
2014-2017 QX60 Hybrid (L50)


APPLIED VIN and DATE: 2013 JX35:
Vehicles built **AFTER** 5N1AL0M(* *)DC 343902 and March 26, 2013
2014-2017 QX60 and QX60 Hybrid: All

APPLIED TRANSMISSION: Vehicles equipped with CVT **ONLY**

SERVICE INFORMATION

Applied vehicles equipped with a CVT have a "cap" that appears to be a fluid level gauge. This "cap" will **NOT** have a gauge or "dipstick". This is normal. Do **NOT** replace the "cap" because it is thought to have a "dipstick".

The fluid level is not checked from this location. The fluid level for applied vehicles is checked from the oil pan (refer to the appropriate section of the Electronic Service Manual (ESM)). Whenever checking, filling, or topping off a CVT's fluid level of an applied vehicle for any reason, use the procedure outlined in the appropriate section of the ESM.



Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, **DO NOT** assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.