

**Classification:**

HA16-006a

**Reference:**

ITB16-037a

**Date:**

October 4, 2016

## 2014-2016 Q50; INCORRECT DIFFERENCE IN HVAC VENT TEMPERATURES

**APPLIED VEHICLES:** 2014-2016 Q50 and Q50 Hybrid (V37)**APPLIED VIN and DATE:** 2014 Q50: ALL

2014-2015 Q50 Hybrid: ALL

2015 Q50 vehicles built before: JN1BV7AR(\*)FM 424062 and December 12, 2015  
JN1BV7AP(\*)FM 359111 and December 12, 20152016 Q50 vehicles built before: JN1CV7AR(\*)GM 250330 and December 16, 2015  
JN1CV7AP(\*)GM 200286 and December 17, 20152016 Q50 Hybrid vehicles built before: JN1AV7AR(\*)GM 530016 and December 16, 2015  
JN1AV7AP(\*)GM 490021 and December 16, 2015

The information in the previous version of  
this bulletin is no longer valid.

Please discard the previous version of this bulletin.