
ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER

IMPORTANT - AII Service Personnel Should Read and Initial in the boxes provided, right.



© 2016 Subaru of America. Inc. All rights reserved.



NUMBER: 15-198-16R

DATE: 05/02/16

REVISED: 11/21/16

SERVICE BULLETIN

APPLICABILITY: 2015-2016MY Legacy and Outback

2015-2016MY Impreza and XV Crosstrek

2016MY Forester

2016MY WRX

SUBJECT: Reprogramming File Availability to Address

Operational Concerns with "Gen 2" Fujitsu-TEN (F10) Navigation and 7" Display Audio Units

IMPORTANT NOTE: Due to the extensive revisions made to the information originally contained in this bulletin, a new bulletin, 15-205-16 has been issued. Please refer to this new bulletin for the latest information regarding this condition.