

Tech Tips

TT 92-14-05

Date: October 24, 2014

2015 Jetta, Passat - Washer Bottle Replacement due to Leaking at the Filler Pipe Seam

When replacing the washer bottle, Do Not separate the filler neck assembly from the tank unit during removal. Please leave all parts together for possible part return and review.

