

9003784

09/20/2017

MY17

DS

## **GPOP - Issue Review System**

**Part Number:** 68197307A\$

**Part Description:** Fuel Delivery System

**Issue Description:** Before replacing the Fuel Pump Module for rough idle or hard starting issue; please ensure that the Powertrain Control Module (PCM) is up to the latest flash level. If the problem persists with the vehicle up to latest PCM flash level, then proceed on replacing the Fuel Pump Module.

~

~

Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.