

Tech Tips

TT 90-16-02 Date: December 16, 2016

2015 - 2017 Golf, GTI, Golf R, Golf Sportwagen – Fuel Range Reads 999 or Higher after Instrument Cluster Replacement

After instrument cluster replacement, the fuel range may read 999 or higher. The new cluster will need to calculate and adjust this value. This is achieved by driving the vehicle several miles.