



Tech Tips

TT 37-16-02

Date: December 9, 2016

**2014 - 2017 Golf GTI, Golf R, Golf Sportwagen – DTC P17C5,
B116229, Transmission Warning or “Put Vehicle in Park”
message in MFI**

For concerns of a Check Engine Light, Transmission Warning, or a “Put Vehicle in Park” warning in the MFI. First scan the vehicle for faults. If the scan returns P17C5 in the ECM or B116229 in steering column electronics, inspect the gear shifter wiring harness near or around the dash support brackets. If a wiring concern (pinched, chafing) is observed, repair as necessary. If the harness is undamaged, replace the shifter assembly.