Audi of America, Inc.



Date: April 2, 2014

To: Audi Dealer Principal, Service Manager, and Parts Manager

From: Audi Product Compliance Subject: Upcoming Update 87D9

AC Pressure/Temperature Sensor 2013 - 2014 All Audi models except TT

Dear Audi Dealer Principal, Service Manager, and Parts Manager:

This communication is to inform you of upcoming Update 87D9.

What vehicles are affected?

There are 41,370 Audi vehicles affected in the U.S. by this Update.

Of the affected vehicles, the following are in dealer inventory:

New Vehicle Inventory: 62 CPO Inventory: 486

What is the issue?

On Audi vehicles manufactured within a specific period, the refrigerant pressure sensor for the air conditioner may fail after a period of time. As a result, the air conditioner compressor is switched off.

What does the repair procedure involve?

Inspect and if neccessary replace the AC pressure/temperature sensor.

When will the Update be available?

This Update will be visible in Elsa and ServiceNet on or about April 3, 2014.

Please refer to the Elsa campaign/action screen for confirmation of whether the Update applies to each specific vehicle. Additionally, this Update is posted on Elsa and ServiceNet for additional information and complete repair instructions.

Consistent with general Audi corporate policy governing Updates, Audi is not notifying consumers. (Updates differ from recalls and service actions; consumers are notified in writing of recalls and service actions.) Each vehicle should be completed when it is in to the dealer for maintenance or any other service visit. Dealer stock vehicles **cannot**, **however**, **be delivered** to consumers until the Update is completed.

To identify any vehicles in your inventory that are affected by this Update, please run the "New and CPO Inventory Open Campaign/Action Listing" report from the AIM system.

Please ensure that every affected vehicle gets the update <u>before delivery to consumers</u>. Your effort is integral in reaching the highest quality expectations of Audi customers.

Thank you for your cooperation and assistance in this important matter.

Audi of America, Inc. 3800 Hamlin Road Auburn Hills, MI 48326 +1 248 754 5000 www.audiusa.com