



Solution

Title (customer effect) ** Tech Tip ** TT - 009 - 2016 - OBD2015/16 Model Year (MY) 2016/2017 Vehicles with U3017 DTC

Cause OBD2015/16 (MY - 2016/2017) Trucks are logging U3017 Fault Code (DTC)

Solution For more information refer to ** Tech Tip ** TT - 009 - 2016 - OBD2015/16 Model Year (MY) 2016/17 Vehicles with U3017 DTC found in the Trucks Dealer Portal under the service tab - Tech Support - Tech Support Tips or click [here](#).

Solution visibility [Dealer distribution](#)

Function(s)/component(s) affected

Function affected TT , 110 EMS , EECU , Diagnostic tool

Function Group

Function Group 2841 Electronic Control Unit

Customer effect

Main customer effect calibration/programming/pairing/missing operation , diagnostics/methodology , efficiency/abnormal behavior , fault code/display

Fault code(s)

OBD 2013 Diagnostic Trouble Codes U3017

Conditions

Vehicle operating mode when driving , when stationary

Frequency of occurrence of problem always

Administration

Author A241298

Last modified by A241298

Creation date 10-10-2017 18:10

Date of last update 11-10-2017 16:10

Status Published

NA_MACK_Vehicle_Range

NA_MACK_Vehicle_Range Cabover , LR , LEU , MRU , Conventional , CHU , CXU , GU , TD

NA_VOLVO_Vehicle_Range

NA_VOLVO_Vehicle_Ra

nge

Conventional , VNR , VNX , VNL , VNM , VHD , VAH

Engine family

Engine family 11L Engine , 13L Engine , 16L Engine , Mack , MP7 , MP8 , MP10

Emission Standard

Emission Standard US16 , US15
