



# Preliminary Information

## PIP5508A PQC 2018 Part Restriction T87A Transmission Control Module

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2018	All	All	All	M3W
Buick	Envision	2018	All	All	All	M3T
Buick	LaCrosse	2018	All	All	All	M3G, M3H
Buick	Regal	2018	All	All	All	M3D, M3F, M3T
Cadillac	ATS	2018	All	All	All	M5N, M5T
Cadillac	CT6	2018	All	All	All	M5N, M5X, MRD
Cadillac	CTS	2018	All	All	All	M5N, M5U
Cadillac	Escalade	2018	All	All	All	M5U, MF6
Chevrolet	Camaro	2018	All	All	All	M5T, M5U, MGL
Chevrolet	Colorado	2018	All	All	All	M5T
Chevrolet	Corvette	2018	All	All	All	M5U
Chevrolet	Cruze	2018	All	All	All	M3D
Chevrolet	Equinox	2018	All	All	All	M3D
Chevrolet	Express	2018	All	All	All	M5U
Chevrolet	Malibu	2018	All	All	All	M3E
Chevrolet	Silverado	2018	All	All	All	M5U, MW7
Chevrolet	Tahoe RST	2018	All	All	L86	MF6
Chevrolet	Traverse	2018	All	All	All	M3V
GMC	Savana	2018	All	All	All	M5U
GMC	Sierra	2018	All	All	All	M5U, MW7
GMC	Terrain	2018	All	All	All	M3H, M3U
GMC	Yukon	2018	All	All	All	MF6

Involved Region or Country	North America
Additional Options (RPO)	N/A
Condition	The T87A Transmission Control Module part number 24279973 is on restriction through GM PQC as part of our ongoing quality improvement efforts to assist Engineering with product concern identification effective on 07/17/2017.
Cause	Your cooperation with this program is greatly appreciated.

If your diagnosis has led to replacement of the TCM, please contact the Product Quality Center (PQC) @ 866-654-7654.

Please complete the questionnaire below before calling the PQC.

What is the customer's concern?

Was the concern duplicated? (Y/N)

List all history and current DTCs in the TCM.

Are any of the DTCs repeatable?

Did the TCM set a P0601, P0604, P0606, or P062F?

Is the condition temperature-related?

If no, continue next question.

If yes, under what conditions?

What SI documents were used for diagnosis?

What step in the document led to replacement?

Are you using a LAN cable or wireless connection for reprogramming?

Were there any previous repairs related to this concern? (Y/N)

Is the vehicle modified with any non-production accessories? (Y/N)

Does the vehicle have a recent history of low battery voltage? (Y/N)

Has the vehicle been jump-started? (Y/N)

Has the battery recently been charged? (Y/N)

Were the wires/harnesses checked for proper routing and free from damage, stretch, pinch, etc. (Y/N)

Have all the TCM grounds been checked (Y/N)

Have the TCM connectors been checked for “backed out” or damaged connector/terminals (Y/N)

Are there any programming issues? (Y/N)

### **Parts Information**

Description	Part Number	QTY
Transmission Control Module	24279973	1

### **Version History**

Version	2
Modified	10/13/2017 - Update to add the 2018 Chevrolet Tahoe RST model.



© 2016 General Motors. All Rights Reserved.