



Diagnostic Application - Windows Internet Explorer
http://localhost:8080/pal2_launch.action?candidateId=DATALOGGER&abortAction=pal2_completed

File Edit View Favorites Tools Help

LAND ROVER SDD TOPIX GCM

Bulletins Workshop Manual Wiring Diagrams Electrical Reference Library

Vehicle Settings Sessions

Session Selected Symptoms DTCs Recommendations Extras Service Functions

0 (OFF)
Keyless vehicle input switch status - Front left unlock pull switch (KVM)

0 (OFF)
Keyless vehicle input switch status - Front right unlock pull switch (KVM)

0 (OFF)
Keyless vehicle input switch status - Rear left unlock pull switch (KVM)

0 (OFF)
Keyless vehicle input switch status - Rear right unlock pull switch (KVM)

Keyless vehicle input switch status - Front right unlock pull switch

Andy Roberts - Discovery Sport (L550) 715271 - 17 Aug 2017 12:07 (150.04 v.275) - NGI:-/:-/004.03/005.01/

The JLR VCI is connected.

Done Trusted sites | Protected Mode: Off 100%





FALE INDIK (Lengkap) jenkins-11-NOV-16-11-50:410s

FCU Diagnostics > Remote Function Actuator [RFA] > Live data

Remote keyless input switch status - Right Front Unlock Full Switch [A113] - Off

Remote keyless input switch status - Right Rear Unlock Full Switch [A113] - Off

Remote keyless input switch status - Left Front Unlock Full Switch [A113] - Off

Remote keyless input switch status - Left Rear Unlock Full Switch [A113] - Off

Time

Jaguar F-Pace X761 (DoIP) VIN: SADCA2AX1JA248100 Model year: 2018 Odometer: 3542 mi 12.1 V

