



Volkswagen



2017 Jetta

Engine	Part	Part Number	Quantity
1.4L CZTA	Oil Filter	04E 115 561 H	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	4.0L (4.2qt)
	Drain Plug Gasket	N-91086801	1
	Air Filter	04E 129 620	1

Engine	Part	Part Number	Quantity
1.8L Turbo: CPRA	Oil Filter	06K 115 562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	5.5L (5.7qt)
	Drain Plug Gasket	N 911 679 01	1
	Air Filter	5C0 129 620	1

Engine	Part	Part Number	Quantity
2.0L Turbo GLI: CPLA, CPPA	Oil Filter	06K 115 562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	5.5L (5.8qt)
	Drain Plug Gasket	N 911 679 01	1
	Air Filter	5C0 129 620	1

Miscellaneous	Part	Part Number	Quantity
Miscellaneous	Pollen Filter (20K Only)	1K0 819 644 B	1
	Driver's Wiper Blade (Left)	5C7 955 425 B	1
	Passenger's Wiper Blade (Right)	5C7 955 426 B	1
	Battery	000 915 105 *	1
	Battery	5K0 915 105 *	1
	Battery	5GM 915 105 *	1

*VIN Required



2017 Jetta



2017 Jetta Service Reminder Reset

Resetting the oil change service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the oil change service reminder can be reset as follows:

Vehicles with text messages:

1. Switch off the ignition.
 2. Press and hold the **0.0/SET** button in the instrument cluster.
 3. Restart the ignition.
 4. Release the button **0.0/SET** button.
 5. Confirm the query in the instrument cluster with the **OK** button on the multi-function steering wheel.
-

Vehicles without text messages:

1. Switch off the ignition.
 2. Press and hold down the **0.0/SET** button in the instrument cluster.
 3. Restart the ignition.
 4. Release the **0.0/SET** button and press the **📄/🕒** button within approximately 20 seconds.
-

Resetting the inspection service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the inspection service reminder can be reset as follows:

Vehicles with text messages:


1. Switch off the ignition.
 2. Switch on the hazard warning lights.
-


Vehicles with text messages:

3. Press and hold down the **0.0/SET** button in the instrument cluster.
 4. Restart the ignition.
 5. Release the **0.0/SET** button.
 6. Confirm the query in the instrument cluster with the **OK** button on the multi-function steering wheel.
 7. Switch off the hazard warning lights.
-

Vehicles without text messages:

1. Switch off the ignition.
 2. Switch on the hazard warning lights.
 3. Press and hold down the **0.0/SET** button in the instrument cluster.
 4. Restart the ignition.
 5. Release the **0.0/SET** button and press the **⊞/⊚** button within approximately 20 seconds.
 6. Switch off the hazard warning lights.
-

 Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.



 If you manually reset the service interval display while flexible oil change service is valid, the “fixed oil change service” will be activated. The service interval will no longer be calculated on an individual basis



Volkswagen



2017 Jetta

-  The service message go out after a few seconds when the engine is running or by pressing the **OK** button on the multi-function steering wheel.
-  If the vehicle battery was disconnected for long periods in vehicles with flexible service, the system cannot calculate the time at which the next service is due. The service displays could then display incorrect information. If this is the case, please heed the maximum permissible service intervals listed in the ⇒ Booklet *Service Schedule*.

For current fluid capacity charts, please refer to the Maintenance section in Elsa.