

VWoA Compliance

Subject: Immediate Action Required - TDI Emissions AEM Requires most recent ODIS Service Diagnostic Content Version

From: VWoA Dealership Communication

Sent: Monday, August 21, 2017 3:23 PM

Subject: Immediate Action Required - TDI Emissions AEM Requires most recent ODIS Service Diagnostic Content Version

Workshop Technology Communication

Dealer Principals	General Managers	Sales	Certified Pre-owned
Service	Parts	Warranty	Finance & Insurance

From: Workshop Technology

Immediate Action Required - TDI Emissions AEM Requires most recent ODIS Service Diagnostic Content Version

Colleagues,

Beginning Tuesday Aug. 22, 2017, the TDI Emissions AEM can only be performed using the most recent ODIS Service Diagnostic Content Version 2.34.7. Attempting to perform this AEM with a lower diagnostic content version will result in a failure message of ERP0219E and the test will be cancelled.

Please ensure that all diagnostic devices in workshop service are updated as soon as possible.

To identify the versions currently installed on a diagnostic device, please refer to ODIS Service - Service Information document title: **VOS-15-02 Online Update Guide - Section 4.0.**

Thank you

Todd Nurnberger
Manager - Workshop Technology

Frank Deluca
Team Leader - Diagnostic Software Support (DTSS)

Workshop Technology