

## **Technical Information**

Service

69/16 ENU 4739

4

Spare Parts Requirements for Brake Caliper for PCCB (I-no. 450, ceramic brake): Use New Part Numbers Available (69/16)

Vehicle Type: **911 Turbo (991)** 

911 Turbo S (991)

911 Turbo Cabriolet (991) 911 Turbo S Cabriolet (991)

Model Year: As of 2014 up to 2017

Equipment: PCCB – Porsche Ceramic Composite Brake (I-no. 450, ceramic brake)

Subject: Brake caliper

Concern: If the front brake caliper needs to be replaced, new part numbers are available.

This should reduce the number of spare parts variants. Once existing inventory has been used up, order

only the new parts numbers.

Parts Info:

Part No. (old, use up existing stock)	Part No. (new)	Designation	Qty.	
991.351.429.33	991.351.429.34	⇒ Fixed caliper on front axle, left	1 ea.	
991.351.430.33	991.351.430.34	⇒ Fixed caliper on front axle, right	1 ea.	

Invoicing: For documentation using PQIS, enter the following coding:

Location (FES5)	46510	PCCB - Front brake disc
Damage type (SA4)	2015	Creaking

References: ⇒ Workshop Manual '473919 Removing and installing front brake calliper'

Service 4739 ENU 69/16

## **Technical Information**

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safety. If a particular condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your authorized Porsche Dealer for the latest information about whether a particular technical bulletin applies to your vehicle. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify the current and correct part numbers. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

Dealership Distribution Routing	Service Manager	 Shop Foreman	 Service Technician	 	 
	Asst. Manager	 Warranty Admin.	 Service Technician	 	 

Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayman®, Macan®, Panamera®, Speedster®, Spyder®, 918 Spyder®, Tiptronic®, VarioCam®, PCM®, PDM®, 911®, RS®, 4S®, FOUR, UNCOMPROMISED®, and the model numbers and the distinctive shapes of the Porsche automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Porsche Cars North America, Inc. believes the specifications to be correct at the time of printing. Specifications, performance standards, standard equipment, options, and other elements shown are subject to change without notice. Some options may be unavailable when a car is built. Some vehicles may be shown with non-U.S. equipment. The information contained herein is for internal authorized Porsche dealer use only and cannot be copied or distributed. Porsche recommends seat belt usage and observance of traffic laws at all times.

Aug 18, 2016 Page 2 of 2