

<b>Reference</b>	SSM73661
<b>Models</b>	F-TYPE / X152
<b>Title</b>	F - Type (X152) - Rear Licence Plate Lamp Inoperative
<b>Category</b>	Body
<b>Last modified</b>	05-Dec-2017 00:00:00
<b>Symptom</b>	108000 Ext. Trim/Accessories

**Content**

Issue: A customer may present a vehicle where the rear number plate lamp requires replacing.

Cause: Under engineering investigation.

Action: Where replacement of rear number plate lamps is determined, please replace the complete decklid finisher assembly which includes, as part of the assembly, license plate lamps and the link lead harness with the latest level components as listed in the aftermarket parts catalogue. Please raise an EPQR and await instructions regarding the return of the parts by reply.

If you are within 200 miles of the Castle Bromwich plant, before undertaking any repair, please raise an EPQR requesting an engineering visit to inspect the vehicle and components 'in situ', and await a response before attempting to rectify the vehicle.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.