

American Honda Motor Co., Inc. 1919 Torrance Boulevard Torrance, CA 90501-2746 Phone (310) 783-2000

MULTI-MODEL: OWNER'S MANUAL #1
REMEDY PARTS SHIPMENT

EMISSION RECALL MULTIPLE MODELS - OWNER'S MANUAL REPLACEMENT

DEALER INVENTORY REPAIR INSTRUCTIONS

Some motorcycles in your dealership's inventory are affected by a recall to replace the Owner's Manual. Enclosed are the remedy Owner's Manuals to repair the affected motorcycles.

American Honda sales records indicate the following affected motorcycles are in your inventory. Please review the Service Bulletin *Multi-Model: Owner's Manual #1* and follow the REPAIR PROCEDURE instructions to replace the original Owner's Manual with the remedy manual enclosed in this box.

If a unit on this list is already sold and delivered, contact your customer and ask them to bring in their vehicle for a free Owner's Manual replacement.

If a unit on this list was involved in a dealer trade, please coordinate the exchange of the manual with the other dealer.

YOUR AFFECTED INVENTORY

Affected Model	VIN	Remedy Owner's Manual Part Number