

Technical Service Bulletin

20 Q3 extended crank time

20 16 79 2045490/1 October 14, 2016.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2015 - 2016	All	Not Applicable
Q3	2017	000001 - 001048	Not Applicable

Condition

Customer may report extended crank time after vehicle parked for more than one hour.

Technical Background

Fuel pressure regulator does not hold pressure.

Production Solution

Improved fuel filter with flange and pressure regulator.

Service

Replace fuel filter with flange according ELSA instructions:

ELSA>Repair Manual>Engine>Fuel Supply – Gasoline Engines>20 Fuel Supply>Fuel Filter>Fuel Filter, Removing and Installing.



Fuel Pump should NOT be replaced for this specific issue.



Technical Service Bulletin

Warranty

Claim Type:	 110 up to 48 Months/50,000 Miles. If vehicle is outside any warranty, this Technical Bulletin is informational only. 				
Service Number:	2031				
Damage Code:	0010				
Labor Operations:	Fuel Filter remove + reinstall	2031 1900	130 TU		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB 2045490/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
See ETKA	Fuel filter with flange	01
See ETKA	Seal Ring	01

Additional Information

All parts and service references provided in this TSB (2045490) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2016 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.