

**June 24, 2014**

ATB 51812 (1406)

## Safety Recall: Civic, CR-V, and Odyssey - Front Passenger's Airbag Inflator Can Be Over-Pressurized

### AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2002-03	Civic	ALL	TBD
2002-03	CR-V	ALL	TBD
2002-03	Odyssey	ALL	TBD

### BACKGROUND

A manufacturing error can produce over-pressurization of the passenger's (front) airbag inflator during airbag deployment. If an affected airbag deploys, the increased internal pressure may cause the inflator casing to rupture. Metal fragments could be propelled upward toward the windshield, or downward toward the front passenger's foot well, possibly causing an injury to vehicle occupants.

This bulletin will be revised once VIN information, the repair procedure, parts information, and warranty claim information are available.

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.