

8/17/16

MY15, 16, 17 LA, LD, LX

GPOP - Issue Review System

Part Number: 05154726A\$, 05154743A\$, 05154744A\$, 05154727A\$, 05154730A\$, 05154731A\$, 05154732A\$, 68243433A\$, 68243432A\$, 68274990A\$, 68274991A\$, 68274992A\$, 68274993A\$, 68274994A\$, 68274995A\$, 68274996A\$, 68274997A\$, 68274998A\$, 68323540A\$, 68323541A\$, 68323542A\$, 68323543A\$, 68323544A\$, 68323545A\$, 68323546A\$, 68323547A\$, 68323548A\$

Part Description: Electric Power Steering Gear

Issue Description: For LA, LD and LX Models ONLY; Before this part is replaced for:

A) Electrical, Communication or DTC issue please contact:
Terry Gavit @ cell (248) 882-6108 terry.gavit@fcagroup.com
Engineering is requesting a copy of VSR to be emailed to the above address.

B) Noise or Mechanical issue please contact:
Barbara Strace @ cell (586) 246-4211.

If you do not receive a return call within 15 minutes, proceed with the repair.

Please be sure to attach a copy of the Vehicle Scan Report on the repair order.

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
